



Sydney CBD

Ipswich QLD

These are two examples (there are many others) which show the reason why peristaltic dosing pumps should not be installed in locations exposed to direct sunlight – It is obvious that in these instances the problem would have been mitigated by the servicing company periodically replacing the pump bladder (each 12 months).

*Ian Childs*

NAM/; F.IPEA; M.SBSE; M.SFS; M.AIES; Aff. CIBSE •

(02) 9594 4477, (02) 8569 1015, 0414 472 042  
e-mail [ian@ndibs.com.au](mailto:ian@ndibs.com.au) internet [www.ndibs.com.au](http://www.ndibs.com.au)  
[www.fireassess.com.au](http://www.fireassess.com.au)